



HUAAN LIMITED TSS Competitive Cross Reference* Guide

| TO-92 Series TSS | | | | | |
|---------------------------|------------------------|--------------------|---------------------------|------------------------|--------------------|
| HUAAN LIMITED Part number | Littelfuse Part number | Bourns Part number | HUAAN LIMITED Part number | Littelfuse Part number | Bourns Part number |
| P0080EA | P0080EAL | - | P1800EB | P1800EBL | - |
| P0300EA | P0300EAL | - | P2100EB | P2100EBL | - |
| P0640EA | P0640EAL | TISP4070M3LM | P2300EB | P2300EBL | - |
| P0720EA | P0720EAL | TISP4080M3LM | P2600EB | P2600EBL | - |
| P0900EA | P0900EAL | TISP4095M3LM | P3100EB | P3100EBL | - |
| P1100EA | P1100EAL | TISP4115M3LM | P3500EB | P3500EBL | - |
| P1300EA | P1300EAL | TISP4145M3LM | P0080EC | P0080ECL | - |
| P1500EA | P1500EAL | TISP4165M3LM | P0300EC | P0300ECL | - |
| P1800EA | P1800EAL | TISP4220M3LM | P0640EC | P0640ECL | TISP4070H3LM |
| P2100EA | P2100EAL | TISP4240M3LM | P0720EC | P0720ECL | TISP4080H3LM |
| P2300EA | P2300EAL | TISP4250M3LM | P0900EC | P0900ECL | TISP4095H3LM |
| P2600EA | P2600EAL | TISP4290M3LM | P1100EC | P1100ECL | TISP4115H3LM |
| P3100EA | P3100EAL | TISP4350M3LM | P1300EC | P1300ECL | TISP4145H3LM |
| P3500EA | P3500EAL | TISP4395M3LM | P1500EC | P1500ECL | TISP4180H3LM |
| P0080EB | P0080EBL | - | P1800EC | P1800ECL | TISP4220H3LM |
| P0300EB | P0300EBL | - | P2100EC | P2100ECL | TISP4240H3LM |
| P0640EB | P0640EBL | - | P2300EC | P2300ECL | TISP4250H3LM |
| P0720EB | P0720EBL | - | P2600EC | P2600ECL | TISP4290H3LM |
| P0900EB | P0900EBL | - | P3100EC | P3100ECL | TISP4350H3LM |
| P1100EB | P1100EBL | - | P3500EC | P3500ECL | TISP4395H3LM |
| P1300EB | P1300EBL | - | - | - | - |
| P1500EB | P1500EBL | - | - | - | - |

Please pay attention: HUAAN LIMITED's Part Number is perfect replacement for Littelfuse and Bourns TSS part number, which circuit and design need not to be changed.

sales@huaandz.com

abc0734@126.com